

*Neighborhood Walk Follow Up Report*

Downtown - Main Street 2006

*6/8/2006*

ID	DATE	LOCATION	PROBLEM	ASSIGNED TO (DEPT)	DEPT CONTACT	STATUS
1	6/8/2006	607 Main Street	defective cornice and paint	B&I	D. Schneider	violations noted and orders are in process
2	6/8/2006	625 Main Street	defective cornice and paint	B&I	D. Schneider	violations noted and orders are in process
3	6/8/2006	627 Main Street	Rusted fire escape	B&I	D. Schneider	violations noted and orders are in process
4	6/8/2006	629 Main Street	Defective chimney and masonry wall	B&I	D. Schneider	violations noted and orders are in process
5	6/8/2006	711 Main Street	Loose wire at fire escape, paint masonry wall	B&I	D. Schneider	violations noted and orders are in process
6	6/8/2006	722 Main Street	Paint Exterior	B&I	D. Schneider	violations noted and orders are in process
7	6/8/2006	718 Main Street	Broken windows and awning needs repair	B&I	D. Schneider	violations noted and orders are in process